

11/4/85

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT  
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Dinosaur NM PARK NUMBER 1400  
STRUCTURE NAME Chew/Pool Creek House STRUCTURE NUMBER HS-344  
(STR1)  
LOCATION OF STRUCTURE Stuntz Reservoir, CO 7.5' PARK LOCATION CODE PG  
Quad  
NATIONAL REGISTER \_\_\_\_\_ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)  
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO

Check all of the following categories for which NPS has treatment responsibility:

Stabilization(☒)Cyclic Maintenance(☒)Routine Maintenance(☒)Approved Ultimate Treatment(☒)

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation	(PP)	Restoration	(RR)	Reconstruction	(CC)
Adaptive Preservation	(AP)	Adaptive Restoration	(AR)	Adaptive Reconstruction	(AC)
Neglect	(NG)	Remove	(RM)	No Approved Treatment	(NO)

Approval Document \_\_\_\_\_ ( ) Document Date: / /

Estimated Treatment Costs \_\_\_\_\_

Stabilization:	\$ _____	Date:	<u>/ /</u>	Level of
Approved Treatment:	\$ _____	Date:	<u>/ /</u>	Estimate: (A) (B) (C)
				Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: ca 1940 Date of Alterations: unknown  
Architect/Designer: Rial Chew Historical Theme(s): Ranching Post 1900 (VII A4  
History of Structure: Rial Chew, (Jack's son) after his marriage, moved to this  
location to establish his ranch. At some time during the house's use he  
apparently added a rear, enclosed porch. Occupied until special use permit expired  
in early 1970s.

Evaluation of Structure: Historic Theme Contributing X Non-Contributing \_\_\_\_\_  
National Register Criteria: A\_X B\_ C\_ D\_ (Include integrity statement)  
Maintains integrity, internal and exterior, maintains historic feeling,  
represents 20th century, western ranching complex.

Bibliography: Rial Chew Interviews, Dinosaur NM.

Representation in Other Surveys: 1974 NRHP form, 1975 LCS Survey

If structure has been removed, how? Not moved Date: / /


Report prepared by: Steven F. Mehls Date: 6/24/85

Condition: Good  
Significance: L  
Documentation: Fair  
Internal Impacts: U/NOA  
External Impacts: U/NOA

LOCATION: Section 6 State Colorado USE: CURRENT INTERIOR USE (NPS 28 CODE) 00  
Township 6N County Moffat Original Use Residence  
Range 104W Intermediate Uses \_\_\_\_\_  
PERIOD OF CONSTRUCTION (NPS 28 CODE) HI

OWNERSHIP: Present Owner: \_\_\_\_\_ NPS DRAWING NO. \_\_\_\_\_  
Original Owner: \_\_\_\_\_ Rial Chew NEGATIVE NO. Roll DNM-7, #34, 35, 36  
Intermediate Owner(s): \_\_\_\_\_

## \*\*\*PHYSICAL DESCRIPTION\*\*\*

TYPE OF STRUCTURE (NPS 28 CODE): BU CHIMNEYS: brick w/ brick cap  
ARCHITECTURAL CHARACTER (STYLE): Ranch, Gabled  
SITE (INCLUDE ORIENTATION OF STRUCTURE):  PORCHES: sun porch - rear - 8' x 21'  
shed roof  
3-4' walls topped with windows &  
OVERALL BUILDING PLAN (FOOTPRINT): "L" WINDOWS: double hung sash- 1 over 1  
OVERALL DIMENSIONS: 34' x 26' Porch - 8' x 21' screens  
COMPOSITION (NPS 28 CODE): WD screens  
STORIES: 1 DOORS: front & rear  
FOUNDATION: 30' ± high/ stucco covered rear - 3 light (vert) over 1 panel  
front - 4 light over 3 panel  
WALLS: hewn log, concrete ADDITIONS: side door nailed shut  
sun porch  
ROOF: wood shingle gable, shed roof porch INTERIOR PLAN:  
2 bedroom, unplumbed bath, kitchen,  
living room  
INTERIOR FINISHES:  
lathe & plaster with paint (ugly)  
carpeted floors  
no electricity

## SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

Exterior whitewashed; only minor repairs needed to interior walls for cabin to be habitable.

11/4/85

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT  
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Dinosaur NM PARK NUMBER 1400  
STRUCTURE NAME Chew/Pool Creek Cabin STRUCTURE NUMBER HS-345  
(STR2)  
LOCATION OF STRUCTURE Stuntz Reservoir, CO 7.5' PARK LOCATION CODE PG  
Quad  
NATIONAL REGISTER \_\_\_\_\_ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)  
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO

Check all of the following categories for which NPS has treatment responsibility:

Stabilization ☒ Cyclic Maintenance ☒ Routine Maintenance ☒ Approved Ultimate Treatment ☒

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation	(PP)	Restoration	(RR)	Reconstruction	(CC)
Adaptive Preservation	(AP)	Adaptive Restoration	(AR)	Adaptive Reconstruction	(AC)
Neglect	(NG)	Remove	(RM)	No Approved Treatment	(NO)

Approval Document \_\_\_\_\_ ( ) Document Date: / /

Estimated Treatment Costs \_\_\_\_\_

Stabilization:	\$ _____	Date:	<u>/ /</u>	Level of
Approved Treatment:	\$ _____	Date:	<u>/ /</u>	Estimate: (A) (B) (C)
				Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: ca 1920 Date of Alterations: unknown  
Architect/Designer: J. Chew/Harry Chew Historical Theme(s): Post 1900 Ranching (VII A4)  
History of Structure: Possibly built by Harry Chew at his homestead site and later moved to present location. Cabin has apparently been maintained and replacement parts substituted over the years (roof sheathing). Jack Chew moved to Pool Creek area from Lodore between 1910 and 1912 to raise livestock, his son Rial, after marriage remained in Pool Creek area to ranch & built a house. Harry Chew, cabin's original owner, patented his homestead in 1930.  
Evaluation of Structure: Historic Theme Contributing x Non-Contributing \_\_\_\_\_  
National Register Criteria: A x B C D (Include integrity statement)  
Evidence indicates this may be a partial reconstruction of cabin; cabin was moved from Harry Chew site at nearby Blue Mountain. Structure retains locational and physical integrity on Rial Chew Ranch as well as historic feeling and association.  
Bibliography: Rial Chew Interviews, Dinosaur NM; E.C. Burdick, "remembering," ms on file at Dinosaur NM; Land Files, Dinosaur NM.  
Representation in Other Surveys: 1975 LCS Survey

If structure has been removed, how? MO Date: / / 1958

Report prepared by: Steven F. Mehls Date: 6/ 24/ 85

Condition: Good  
Significance: L  
Documentation: Fair  
Internal Impacts: NOA/POP  
External Impacts: L/POP

CONTINUATION FROM FRONT SHEET - STRUCTURE NAME Chew/Pool Creek Cabin

LOCATION: Section 6 State Colorado USE: CURRENT INTERIOR USE (NPS 28 CODE) OT  
 Township 6N County Moffat Original Use Residence storage  
 Range 104W Intermediate Uses Same  
 PERIOD OF CONSTRUCTION (NPS 28 CODE) HI


OWNERSHIP: Present Owner: NPS DRAWING NO. \_\_\_\_\_  
 Original Owner: Harry Chew NEGATIVE NO. Roll DNM-7, #32, 33  
 Intermediate Owner(s): Rial Chew

\*\*\*PHYSICAL DESCRIPTION\*\*\*

TYPE OF STRUCTURE (NPS 28 CODE): BU CHIMNEYS: 1 hole, SE corner, stovepipe size

ARCHITECTURAL CHARACTER (STYLE): Ranch, Log, roof cabin

SITE (INCLUDE ORIENTATION OF STRUCTURE):



OVERALL BUILDING PLAN (FOOTPRINT): Rectangle

OVERALL DIMENSIONS: 23' x 16' 10"

COMPOSITION (NPS 28 CODE): WD

STORIES: 1

FOUNDATION:

field stone/log - low

WALLS: log (dressed) concrete chinking/dawbing & RR ties

ROOF: Gable, exposed purlin, plankwood, 2 x 4s & metal sheeting

PORCHES: none

WINDOWS: 2 one north, one south side sliding

DOORS: paneled (5 panels)

ADDITIONS: none

INTERIOR PLAN: open

INTERIOR FINISHES: plywood, tile (linoleum floor)

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

Not in original location, said to have been moved in to present location from Harry Chew cabin area

11/4/86

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT  
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Dinosaur NM PARK NUMBER 1400  
STRUCTURE NAME Chew/Pool Creek Root Cellar STRUCTURE NUMBER HS-346  
(STR 3)  
LOCATION OF STRUCTURE Stuntz Reservoir, CO 7.5' PARK LOCATION CODE PG  
Quad  
NATIONAL REGISTER \_\_\_\_\_ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)  
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO

Check all of the following categories for which NPS has treatment responsibility:

Stabilization(☒) Cyclic Maintenance(☒) Routine Maintenance(☒) Approved Ultimate Treatment(☒)

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation	(PP)	Restoration	(RR)	Reconstruction	(CC)
Adaptive Preservation	(AP)	Adaptive Restoration	(AR)	Adaptive Reconstruction	(AC)
Neglect	(NG)	Remove	(RM)	No Approved Treatment	(NO)

Approval Document \_\_\_\_\_ ( ) Document Date: / /

Estimated Treatment Costs \_\_\_\_\_

Stabilization:	\$ _____	Date:	<u>/ /</u>	Level of
Approved Treatment:	\$ _____	Date:	<u>/ /</u>	Estimate: (A) (B) (C)
				Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: ca 1920 Date of Alterations: unknown  
Architect/Designer: R. Chew Historical Theme(s): Post 1900 Ranching (VII A4)  
History of Structure: Built to serve as storage area for food items as part of  
the Chew Ranch operation at Pool Creek, possibly as expansion or replacement for  
another root cellar ruins (excavation/stone line wall) nearby. Used until special  
use permit expired in 1970s.

Evaluation of Structure: Historic Theme Contributing x Non-Contributing \_\_\_\_\_  
National Register Criteria: A X B C D (Include integrity statement)  
This root cellar is deteriorating but retains enough integrity to make style and  
function readily apparent. Contributes to historic feeling of the ranch.

Bibliography: Rial Chew Interviews, Dinosaur NM; Land Files, Dinosaur NM;  
E. C. Burdick, "Remembering," ms. on file, Dinosaur NM, Quarry VC.  
Representation in Other Surveys: 1975 LCS Survey

If structure has been removed, how? OT/Not moved Date: / /

Report prepared by: Steven F. Mehls Date: 6 / 24 / 85

Condition: Fair  
Significance: L  
Documentation: Fair  
Internal Impacts: M/WEA  
External Impacts: M/WEA

LOCATION: Section 6 State Colorado  
Township 6N County Moffat  
Range 104W

USE: CURRENT INTERIOR USE (NPS 28 CODE) 00/ZZ  
Original Use Food storage  
Intermediate Uses \_\_\_\_\_  
• PERIOD OF CONSTRUCTION (NPS 28 CODE) HI

OWNERSHIP: Present Owner: NPS  
Original Owner: Rial Chew  
Intermediate Owner(s): \_\_\_\_\_

DRAWING NO. \_\_\_\_\_  
NEGATIVE NO. Roll DNM-8, #2, 3

## \*\*\*PHYSICAL DESCRIPTION\*\*\*

(DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.)

Type: OT/Root Cellar

Character: Vernacular

Footprint: Rectangle - 1 story  
17' x 11' for cellar (overall)  
7' x 2'6" for entry


Composition: WD/EA

Walls: log (undressed) & soil collapsing

Roof: pole, plastic sheeting, soil

Doors: 1 board and batten

Interior Finish: log/soil



SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

11/4/8

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT  
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Dinosaur NM PARK NUMBER 1400  
STRUCTURE NAME Chew/Pool Creek Outhouse STRUCTURE NUMBER HS-347  
(STR 4)  
LOCATION OF STRUCTURE Stuntz Reservoir, CO 7.5' PARK LOCATION CODE PG  
Quad  
NATIONAL REGISTER \_\_\_\_\_ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)  
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO

Check all of the following categories for which NPS has treatment responsibility:

Stabilization ☒ Cyclic Maintenance ☒ Routine Maintenance ☒ Approved Ultimate Treatment ☒

---

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation (PP)	Restoration (RR)	Reconstruction (CC)
Adaptive Preservation (AP)	Adaptive Restoration (AR)	Adaptive Reconstruction (AC)
Neglect (NG)	Remove (RM)	No Approved Treatment (NO)

Approval Document \_\_\_\_\_ ( ) Document Date: / /

Estimated Treatment Costs \_\_\_\_\_

Stabilization:	\$ _____	Date: <u>/ /</u>	Level of Estimate: (A) (B) (C)
Approved Treatment:	\$ _____	Date: <u>/ /</u>	Estimator: (Region) (DSC) (A&E)

---

STATEMENT OF SIGNIFICANCE:

Date of Construction: ca 1930s Date of Alterations: unknown  
Architect/Designer: R. Chew Historical Theme(s): Post 1900 Ranching (VII A4)  
History of Structure: Built by Jack Chew as part of his ranch complex to serve as comfort station, used until 1970s when special use permit expired. May have been used sporadically since by NPS staff & park visitors. Plywood & fiberboard may have been used to replace earlier walls.

---

Evaluation of Structure: Historic Theme Contributing ☒ Non-Contributing \_\_\_\_\_  
National Register Criteria: A XB C D (Include integrity statement)  
Retains integrity of location & setting. Maintains historic feeling. May be other unlocated outhouse pits in the area.

---

Bibliography: Rial Chew Interviews, Dinosaur NM; Land Files, Dinosaur NM.

---

Representation in Other Surveys: 1975 LCS Survey

---

If structure has been removed, how? NO Date: unknown

---


Report prepared by: Steven F. Mehls Date: 6/24 85

Condition: Good  
Significance: L  
Documentation: Fair  
Internal Impacts: L/NOA  
External Impacts: L/NOA

LOCATION: Section 6 State Colorado USE: CURRENT INTERIOR USE (NPS 28 CODE) 00  
Township 6N County Moffat Original Use Relief  
Range 104W Intermediate Uses \_\_\_\_\_  
PERIOD OF CONSTRUCTION (NPS 28 CODE) HI

OWNERSHIP: Present Owner: NPS DRAWING NO. \_\_\_\_\_  
Original Owner: Rial Chew NEGATIVE NO. Roll DNM-7, #37  
Intermediate Owner(s): \_\_\_\_\_

## \*\*\*PHYSICAL DESCRIPTION\*\*\*

TYPE OF STRUCTURE (NPS 28 CODE): BU CHIMNEYS: None  
ARCHITECTURAL CHARACTER (STYLE): Vernacular  
SITE (INCLUDE ORIENTATION OF STRUCTURE):   
OVERALL BUILDING PLAN (FOOTPRINT): square WINDOWS: None  
OVERALL DIMENSIONS: \_\_\_\_\_  
COMPOSITION (NPS 28 CODE): WD DOORS: New Plywood  
STORIES: 1 ADDITIONS: None  
FOUNDATION: on grade  
WALLS: Fiberboard & 2x4s/wood INTERIOR PLAN: 2 holer  
ROOF: gable plank & tar paper roof INTERIOR FINISHES: fiberboard

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:



11/4/12

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT  
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Dinosaur NM PARK NUMBER 1400  
STRUCTURE NAME John Chew Dugout STRUCTURE NUMBER HS-348  
(STR 5)  
LOCATION OF STRUCTURE Stuntz Reservoir, CO 7.5' PARK LOCATION CODE PG  
Quad  
NATIONAL REGISTER \_\_\_\_\_ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)  
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO

Check all of the following categories for which NPS has treatment responsibility:

Stabilization ☒ Cyclic Maintenance ☒ Routine Maintenance ☒ Approved Ultimate Treatment ☒

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation	(PP)	Restoration	(RR)	Reconstruction	(CC)
Adaptive Preservation	(AP)	Adaptive Restoration	(AR)	Adaptive Reconstruction	(AC)
Neglect	(NG)	Remove	(RM)	No Approved Treatment	(NO)

Approval Document \_\_\_\_\_ ( ) Document Date: / /  
Estimated Treatment Costs \_\_\_\_\_

Stabilization:	\$ _____	Date:	<u>/ /</u>	Level of	
Approved Treatment:	\$ _____	Date:	<u>/ /</u>	Estimate:	(A) (B) (C)
				Estimator:	(Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: ca/19/02 Date of Alterations: unknown  
Architect/Designer: J. Chew Historical Theme(s): Post 1900 Ranching (VII A4)  
History of Structure: Said to be dugout used by Pat Moran to settle his claim;  
later bought by John Chew (1910); converted to root cellar after completion  
of John Chew Cabin

Evaluation of Structure: Historic Theme Contributing ☒ Non-Contributing \_\_\_\_\_  
National Register Criteria: A X B C D (Include integrity statement)  
Building has collapsed roof, partial stone & wood walls, structural remains do  
not make original function readily apparent

Bibliography: Rial Chew Interviews, Dinosaur NM; Land Files, Dinosaur NM.

Representation in Other Surveys: 1975 LCS Survey

If structure has been removed, how? CG/not moved Date: / /

Report prepared by: Steven F. Mehls Date: 6/24/35

Condition: Poor  
Significance: L  
Documentation: Fair  
Internal Impacts: S/NOA  
External Impacts: S/NOA

LOCATION: Section 6 State Colorado USE: CURRENT INTERIOR USE (NPS 28 CODE) ZZ  
Township 6N County Moffat Original Use Residence  
Range 104W Intermediate Uses \_\_\_\_\_  
PERIOD OF CONSTRUCTION (NPS 28 CODE) HI

OWNERSHIP: Present Owner: NPS DRAWING NO. \_\_\_\_\_  
Original Owner: Chew NEGATIVE NO. Roll DNM-8, #4  
Intermediate Owner(s): \_\_\_\_\_

## \*\*\*PHYSICAL DESCRIPTION\*\*\*

(DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.)

Type: OT/dugout


Style: Vernacular

Footprint: Rectangle; 13'9" x 12'6"

Composition: ST/EA

All that remains are two stone walls & depression. No roof.

Contains cultural debris - glass fragments



SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

11/4/86

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT  
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Dinosaur NM PARK NUMBER 1400  
STRUCTURE NAME Chew/Pool Creek Chicken Coops STRUCTURE NUMBER HS-349  
(STR 6)  
LOCATION OF STRUCTURE Stuntz Reservoir, CO 7.5' PARK LOCATION CODE PG  
Quad  
NATIONAL REGISTER \_\_\_\_\_ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)  
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO

Check all of the following categories for which NPS has treatment responsibility:

Stabilization ☒ Cyclic Maintenance ☒ Routine Maintenance ☒ Approved Ultimate Treatment ☒

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation	(PP)	Restoration	(RR)	Reconstruction	(CC)
Adaptive Preservation	(AP)	Adaptive Restoration	(AR)	Adaptive Reconstruction	(AC)
Neglect	(NG)	Remove	(RM)	No Approved Treatment	(NO)

Approval Document \_\_\_\_\_ ( ) Document Date: / /

Estimated Treatment Costs \_\_\_\_\_

Stabilization:	\$ _____	Date:	<u>/ /</u>	Level of	
Approved Treatment:	\$ _____	Date:	<u>/ /</u>	Estimate:	(A) (B) (C)
				Estimator:	(Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: ca/1930 Date of Alterations: unknown  
Architect/Designer: J. Chew Historical Theme(s): Post 1900 Ranching (VII A4)  
History of Structure: Built by Jack Chew as part of his Pool Creek ranch  
operations to house poultry, probably abandoned when Chews moved out of the  
ranch

Evaluation of Structure: Historic Theme Contributing x Non-Contributing \_\_\_\_\_  
National Register Criteria: A\_x B\_ C\_ D\_ (Include integrity statement)

Retains structural, locational integrity making function and appearance readily  
apparent. Maintains historic feeling and association with the rest of the  
ranch complex.

Bibliography: Rial Chew Interviews, Dinosaur NM; Land Files, Dinosaur NM.

Representation in Other Surveys: 1975 LCS Survey

If structure has been removed, how? OT/not moved Date: / /

Report prepared by: Steven F. Mehls Date: 6 / 24 / 85

Condition: Good  
Significance: L  
Documentation: Fair  
Internal Impacts: U  
External Impacts: NOA

CONTINUATION FROM FRONT SHEET - STRUCTURE NAME Chew/Pool Creek Chicken Coop

LOCATION: Section 6 State Colorado USE: CURRENT INTERIOR USE (NPS 28 CODE) 00  
 Township 6N County Moffat Original Use Livestock Raising  
 Range 104W Intermediate Uses \_\_\_\_\_  
 PERIOD OF CONSTRUCTION (NPS 28 CODE) HT

OWNERSHIP: Present Owner: NPS DRAWING NO. \_\_\_\_\_  
 Original Owner: Chew NEGATIVE NO. Roll DNM-3, #5, 6  
 Intermediate Owner(s): \_\_\_\_\_

\*\*\*PHYSICAL DESCRIPTION\*\*\*

TYPE OF STRUCTURE (NPS 28 CODE): BH/fe CHIMNEYS: None  
 ARCHITECTURAL CHARACTER (STYLE): Vernacular PORCHES: None  
 SITE (INCLUDE ORIENTATION OF STRUCTURE): shed enclosure rooted and fenced area Echo Park Road N WINDOWS: none  
 OVERALL BUILDING PLAN (FOOTPRINT): rectangle DOORS: One opening  
 OVERALL DIMENSIONS: 14' x 26'6" shed is 13'6" x 14' ADDITIONS: none  
 COMPOSITION (NPS 28 CODE): WD/MT INTERIOR PLAN: open  
 STORIES: 1 INTERIOR FINISHES: dressed log  
 FOUNDATION: on grade

WALLS: dressed log; L notched, no daubing left

ROOF: gable, pole & soil

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

some wood rotting

#14/16

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT  
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Dinosaur NM PARK NUMBER 1400  
STRUCTURE NAME Chew/Pool Creek Garage (Ralph Chew Cabin) STRUCTURE NUMBER HS-350  
(STR 7)  
LOCATION OF STRUCTURE Stuntz Reservoir, CO 7.5' PARK LOCATION CODE PG  
Quad  
NATIONAL REGISTER \_\_\_\_\_ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)  
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO

Check all of the following categories for which NPS has treatment responsibility:

Stabilization ☒ Cyclic Maintenance ☒ Routine Maintenance ☒ Approved Ultimate Treatment ☒

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation	(PP)	Restoration	(RR)	Reconstruction	(CC)
Adaptive Preservation	(AP)	Adaptive Restoration	(AR)	Adaptive Reconstruction	(AC)
Neglect	(NG)	Remove	(RM)	No Approved Treatment	(NO)

Approval Document \_\_\_\_\_ ( ) Document Date: / /

Estimated Treatment Costs \_\_\_\_\_

Stabilization:	\$ _____	Date:	<u>/ /</u>	Level of
Approved Treatment:	\$ _____	Date:	<u>/ /</u>	Estimate: (A) (B) (C)
				Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: ca 1920 Date of Alterations: none / apparent after move  
Architect/Designer: J. Chew Historical Theme(s): Post 1900 Ranching (VII A4)  
History of Structure: Built by Jack Chew and family as part of his ranching  
complex; abandoned when special use permit expired in early 1970s. The cabin  
originally had been part of Ralph Chew homestead, then moved to present site by  
Rial Chew for use as a garage. Original location was on Blue Mountain.

Evaluation of Structure: Historic Theme Contributing x Non-Contributing \_\_\_\_\_  
National Register Criteria: A x B C D (Include integrity statement)

Structure retains locational and physical integrity on Rial Chew Ranch as well as  
historic feeling and association, serving as unique example within Dinosaur NM of  
adaptation of traditional log architecture to new technology - the automobile

Bibliography: Rial Chew Interviews, Dinosaur NM: Land Files, Dinosaur NM.

Representation in Other Surveys: 1975 LCS Survey

If structure has been removed, how? MO Date: / /1937

Report prepared by: Steven F. Mehls Date: 6 /24/85

Condition: Good

Significance: L

Documentation: Fair

Internal Impacts: U/NOA


External Impacts: U/NOA

CONTINUATION FROM FRONT SHEET - STRUCTURE NAME Chew/Pool Creek Garage

LOCATION: Section 6 State Colorado USE: CURRENT INTERIOR USE (NPS 28 CODE) 00  
 Township 6N County Moffat Original Use Residence  
 Range 104W Intermediate Uses Vehicle storage  
 PERIOD OF CONSTRUCTION (NPS 28 CODE) HI

OWNERSHIP: Present Owner: NPS DRAWING NO. \_\_\_\_\_  
 Original Owner: Ralph Chew NEGATIVE NO. Roll DNM-8, #7, 8  
 Intermediate Owner(s): Rial Chew

\*\*\*PHYSICAL DESCRIPTION\*\*\*

TYPE OF STRUCTURE (NPS 28 CODE): BU CHIMNEYS: None  
 ARCHITECTURAL CHARACTER (STYLE): Ranch, log roof  
 SITE (INCLUDE ORIENTATION OF STRUCTURE):  PORCHES: Front overhang  
 OVERALL BUILDING PLAN (FOOTPRINT): Rectangle WINDOWS: 1 opening  
 OVERALL DIMENSIONS: 17' x 29'  
 COMPOSITION (NPS 28 CODE): WD DOORS: Board & batten, double & above normal height & width; W. side (toward house) single Board & batten  
 STORIES: 1 ADDITIONS: None  
 FOUNDATION: On Grade  
 WALLS: Dressed log - saddle notched; mud dawb & chinking INTERIOR PLAN: Open  
 ROOF: exposed purlins, plank & metal sheeting gable INTERIOR FINISHES: log, w/ split logs over gaps between logs

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

11/1/86

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT  
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Dinosaur NM PARK NUMBER 1400  
STRUCTURE NAME Chew Granary/Jenkins Cabin STRUCTURE NUMBER HS-351  
(STR 8)  
LOCATION OF STRUCTURE Stuntz Reservoir, CO 7.5' PARK LOCATION CODE PG  
quad  
NATIONAL REGISTER \_\_\_\_\_ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)  
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO

Check all of the following categories for which NPS has treatment responsibility:

Stabilization ☒ Cyclic Maintenance ☒ Routine Maintenance ☒ Approved Ultimate Treatment ☒

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation	(PP)	Restoration	(RR)	Reconstruction	(CC)
Adaptive Preservation	(AP)	Adaptive Restoration	(AR)	Adaptive Reconstruction	(AC)
Neglect	(NG)	Remove	(RM)	No Approved Treatment	(NO)

Approval Document \_\_\_\_\_ ( ) Document Date: / /

Estimated Treatment Costs \_\_\_\_\_

Stabilization:	\$ _____	Date:	<u>/ /</u>	Level of
Approved Treatment:	\$ _____	Date:	<u>/ /</u>	Estimate: (A) (B) (C)
				Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: ca/1920 Date of Alterations: unknown  
Architect/Designer: Jenkins Historical Theme(s): Post 1900 Ranching (VII A4)  
History of Structure: Moved to site by Rial Chew as part of Rial Chew's ranching complex; served as granary. Prior to move it had been Jenkins Homestead Cabin.

Evaluation of Structure: Historic Theme Contributing X Non-Contributing \_\_\_\_\_  
National Register Criteria: AX B C D (Include integrity statement)

Structure retains locational and physical integrity on Rial Chew Ranch as well as historic feeling and association, serving as unique example of adaptation to use log cabin as granary.

Bibliography: Rial Chew Interviews, Dinosaur NM; Land Files, Dinosaur NM.

E.C. Burdick, "Remembering," ms on file at Dinosaur NM.

Representation in Other Surveys: 1975 LCS Survey

If structure has been removed, how? NO Date: / / 1937

Report prepared by: Steven F. Mehls Date: 6 /24/ 85

Condition: Good

Significance: L

Documentation: Fair


Internal Impacts: L/POP

External Impacts: L/POP

LOCATION: Section 6 State Colorado USE: CURRENT INTERIOR USE (NPS 28 CODE) 00  
Township 6N County Moffat Original Use Residence  
Range 104W Intermediate Uses Grain Storage  
PERIOD OF CONSTRUCTION (NPS 28 CODE) HI

OWNERSHIP: Present Owner: NPS DRAWING NO. \_\_\_\_\_  
Original Owner: Jenkins NEGATIVE NO. Roll DNM-8, # 9, 10  
Intermediate Owner(s): Rial Chew

## \*\*\*PHYSICAL DESCRIPTION\*\*\*

TYPE OF STRUCTURE (NPS 28 CODE): BII CHIMNEYS: None  
ARCHITECTURAL CHARACTER (STYLE): Ranch, log roof  
SITE (INCLUDE ORIENTATION OF STRUCTURE):   
OVERALL BUILDING PLAN (FOOTPRINT): Rectangle PORCHES: Roof overhang  
OVERALL DIMENSIONS: 20' x 14'6" WINDOWS: None left - one boarded up - rear wall  
COMPOSITION (NPS 28 CODE): WD DOORS: 1 board & batten, metal hinges  
STORIES: 1 ADDITIONS: None  
FOUNDATION: random field stone/wood water table  
WALLS: Dressed/L'notched logs, some flat, some tapered INTERIOR PLAN: open room, closed on E. Wall  
ROOF: Gable, exposed purlin, wood planks, asphalt sheet covers INTERIOR FINISHES: wood planking

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:



11/4/86

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT  
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Dinosaur NM PARK NUMBER 1400  
STRUCTURE NAME Chew Loafing Shed STRUCTURE NUMBER HS-353  
(STR 10)  
LOCATION OF STRUCTURE Stuntz Reservoir, CO 7.5' PARK LOCATION CODE PG  
NATIONAL REGISTER \_\_\_\_\_ DATE:      /      /      Quad \_\_\_\_\_ MANAGEMENT CATEGORY: (A) (B) (C) (D)  
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO

Check all of the following categories for which NPS has treatment responsibility:

Stabilization ☒ Cyclic Maintenance ☒ Routine Maintenance ☒ Approved Ultimate Treatment ☒

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation	(PP)	Restoration	(RR)	Reconstruction	(CC)
Adaptive Preservation	(AP)	Adaptive Restoration	(AR)	Adaptive Reconstruction	(AC)
Neglect	(NG)	Remove	(RM)	No Approved Treatment	(NO)

Approval Document \_\_\_\_\_ ( ) Document Date:      /      /     

Estimated Treatment Costs \_\_\_\_\_

Stabilization:	\$	<u>    </u>	Date:	<u>    </u> / <u>    </u> / <u>    </u>	Level of
Approved Treatment:	\$	<u>    </u>	Date:	<u>    </u> / <u>    </u> / <u>    </u>	Estimate: (A) (B) (C)
					Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: ca/1920 Date of Alterations: unknown  
Architect/Designer: J. Chew Historical Theme(s): Post-1900 Ranching (VII A4)  
History of Structure: Built by Jack Chew and family as part of Pool Creek ranch  
complex, structure had no sides, only corner posts and gable roof - used either  
as shade or shelter for storage of hay/stock feed for animals at nearby  
corrals

Evaluation of Structure: Historic Theme Contributing X Non-Contributing \_\_\_\_\_  
National Register Criteria: A X B C D (Include integrity statement)  
maintains integrity of setting and location, roof is missing, roof frame partially  
missing

Bibliography: Rial Chew Interviews, Dinosaur NM.

Representation in Other Surveys: 1975 LCS Survey

If structure has been removed, how? OT-original location Date:      /      /     

Report prepared by: Steven F. Mehls Date: 6 /24 / 85

Condition: Fair  
Significance: L  
Documentation: Fair  
Internal Impacts: U  
External Impacts: M/WEA

LOCATION: Section 6 State Colorado USE: CURRENT INTERIOR USE (NPS 28 CODE) 00  
Township 6N County Moffat Original Use Livestock Tending  
Range 104W Intermediate Uses \_\_\_\_\_  
PERIOD OF CONSTRUCTION (NPS 28 CODE) H1

OWNERSHIP: Present Owner: NPS DRAWING NO. \_\_\_\_\_  
Original Owner: Chews NEGATIVE NO. DNM-Roll 8, #12  
Intermediate Owner(s): \_\_\_\_\_

---

---

**\*\*\*PHYSICAL DESCRIPTION\*\*\***

(DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.)


4 poles, roof frame, gable end collapsed

15'x10'

SE of Corrals on Echo Park Road

Type: FE

Material: WD



---

---

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

114/85

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT  
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Dinosaur NM PARK NUMBER 1400  
STRUCTURE NAME Chew "Trout Farm" & Irrigation Ditch STRUCTURE NUMBER HS-354  
(STR 13)  
LOCATION OF STRUCTURE Stuntz Reservoir, CO. 7.5' Quad PARK LOCATION CODE PG  
NATIONAL REGISTER \_\_\_\_\_ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)  
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO

Check all of the following categories for which NPS has treatment responsibility:

Stabilization ☒ Cyclic Maintenance ☒ Routine Maintenance ☒ Approved Ultimate Treatment ☒

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation	(PP)	Restoration	(RR)	Reconstruction	(CC)
Adaptive Preservation	(AP)	Adaptive Restoration	(AR)	Adaptive Reconstruction	(AC)
Neglect	(NG)	Remove	(RM)	No Approved Treatment	(NO)

Approval Document \_\_\_\_\_ ( ) Document Date: / /

Estimated Treatment Costs \_\_\_\_\_

Stabilization:	\$ _____	Date: <u>/ /</u>	Level of Estimate:	(A) (B) (C)
Approved Treatment:	\$ _____	Date: <u>/ /</u>	Estimator:	(Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: 1820s Date of Alterations: None/Apparent  
Architect/Designer: Jack Chew Historical Theme(s): Post 1900 Ranching (VII A4)  
History of Structure: Built by Chew family as a system to divert Pool Creek to a large hay meadow; ditch served a system of small trenches through the meadow and also fed a pond in which Chews hoped to start a trout farm that never came to pass. One of the few extant examples in Dinosaur NM of such a water diversion project.

Evaluation of Structure: Historic Theme Contributing x Non-Contributing \_\_\_\_\_  
National Register Criteria: A x B C D (Include integrity statement)  
Retains integrity of location and even with minor erosion the water diversion purpose of the structure remains evident

Bibliography: J. Ballard, personal communication; 6/24/85; Rial Chew Interviews, Dinosaur NM.

Representation in Other Surveys: Machinery in the irrigated meadow photographed in 1975 LCS Survey

If structure has been removed, how? OT-original location Date: / /

Report prepared by: Steven F. Mehls Date: 6/24/85

Condition: Fair  
Significance: L  
Documentation: Fair  
Internal Impacts: M/ERO  
External Impacts: M/ERO

LOCATION: Section 6 State Colorado USE: CURRENT INTERIOR USE (NPS 28 CODE) 00  
Township 6N County Moffat Original Use Water supply for Agri.  
Range 104W Intermediate Uses \_\_\_\_\_  
PERIOD OF CONSTRUCTION (NPS 28 CODE) HI

OWNERSHIP: Present Owner: NPS DRAWING NO. \_\_\_\_\_  
Original Owner: Chews NEGATIVE NO. Roll DNM-3, #18, 19  
Intermediate Owner(s): \_\_\_\_\_

---

**\*\*\*PHYSICAL DESCRIPTION\*\*\***

(DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.)

Earth ditch along W. hill of Chew hay meadow approximately 24" deep 4' wide ext. bank to bank.

300 yards  $\pm$  SW Chew house complex

"Trout Farm" is dammed pond approximately 300'x150' on W. edge of Chew hay meadow, mid-way N-S in meadow


Can be seen on route to P. Lynch Pool Creek Cave

Dam approx. 6' to 7' high

Hay rake in vicinity(in meadow )

Type of Structure: ES/WS/CA

Material: EA



• Meadow

→ Z

---

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

11/4/85

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT  
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Dinosaur NM PARK NUMBER 1400  
STRUCTURE NAME Chew Hay Corral STRUCTURE NUMBER HS-355  
(STR 14)  
LOCATION OF STRUCTURE Stuntz Reservoir, CO 7.5' Quad PARK LOCATION CODE PG  
NATIONAL REGISTER \_\_\_\_\_ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)  
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO

Check all of the following categories for which NPS has treatment responsibility:

Stabilization ☒ Cyclic Maintenance ☒ Routine Maintenance ☒ Approved Ultimate Treatment ☒

---

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation	(PP)	Restoration	(RR)	Reconstruction	(CC)
Adaptive Preservation	(AP)	Adaptive Restoration	(AR)	Adaptive Reconstruction	(AC)
Neglect	(NG)	Remove	(RM)	No Approved Treatment	(NO)

Approval Document \_\_\_\_\_ ( ) Document Date: / /  
Estimated Treatment Costs \_\_\_\_\_

Stabilization:	\$ _____	Date:	<u>/ /</u>	Level of
Approved Treatment:	\$ _____	Date:	<u>/ /</u>	Estimate: (A) (B) (C)
				Estimator: (Region) (DSC) (A&E)

---

STATEMENT OF SIGNIFICANCE:

Date of Construction: Post 1920 Date of Alterations: NA / /  
Architect/Designer: J./R. Chew Historical Theme(s): Post 1900 Ranching (VII A4)  
History of Structure: Corral structure built for storage of hay cut in  
nearby hay meadow to be winter feed for livestock, abandoned 1960s when  
ranching in the area ended

---

Evaluation of Structure: Historic Theme Contributing x Non-Contributing \_\_\_\_\_  
National Register Criteria: A x B C D (Include integrity statement)  
Retains integrity of setting, despite minor deterioration, function,  
methods of construction and purpose remain obvious

---

Bibliography: J. Ballard Personal Communication 6/24/85; Rial Chew Interviews,  
Dinosaur NM.  
Representation in Other Surveys: None (Chew Ranch in 1975 LCS Survey)

---

If structure has been removed, how? OT - original site Date: / /

---

Report prepared by: Steven F. Mehls Date: 6/24/85

Condition: Good  
Significance: L  
Documentation: Fair  
Internal Impacts: U  
External Impacts: L/NOA

LOCATION: Section 6 State Colorado USE: CURRENT INTERIOR USE (NPS 28 CODE) 00  
Township 6N County Moffat Original Use Livestock Tending  
Range 104W Intermediate Uses \_\_\_\_\_  
PERIOD OF CONSTRUCTION (NPS 28 CODE) HI \_\_\_\_\_

OWNERSHIP: Present Owner: NPS DRAWING NO. \_\_\_\_\_  
Original Owner: Chews NEGATIVE NO. Roll DNM-8, #20, 21  
Intermediate Owner(s): \_\_\_\_\_

---

**\*\*\*PHYSICAL DESCRIPTION\*\*\***



(DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.)

32'x70' upright wired plank (like snow fence), pole & wire corral

300 yards + West-southwest of Chew House

Composition: WD/MT

Type: FE




To Ranch house



---

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:



CHew RANCH COMPLEX DINOSAUR NATIONAL  
MONUMENT MOFFAT COUNTY, COLORADO

- HS-344 -- Rial Chew House
- HS-345 -- Harry Chew/Pool Creek Cabin
- HS-346 -- Chew Root Cellar
- HS-347 -- Chew Outhouse
- HS-348 -- John Chew Dugout
- HS-349 -- Chew Chicken Coops
- HS-350 -- Chew Garage(Ralph Chew Cabin)
- HS-351 -- Chew Granary(Jenkins Cabin)
- HS-352 -- Chew Corrals
- HS-353 -- Chew Loafing Shed
- HS-354 -- Chew "Trout Farm"/irrigation ditch
- HS-355 -- Chew Hay Corral

\*\*\* = Fenceline

■ = Contributing

□ = Non-contributing

UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
INVENTORY -- NOMINATION FORM**

FOR NPS USE ONLY	
RECEIVED	11/14/86
DATE ENTERED	

CONTINUATION SHEET Geographical Data ITEM NUMBER 10 PAGE 2

Geographical Data -- Chew Ranch Complex

Acreage: 80 acres

UTM References:	Zone	Northing	Easting
	12	44-84-960	6-68-900
by	12	44-84-900	6-68-000
by	12	44-84-500	6-67-940
by	12	44-84-780	6-68-900

Verbal Boundary Description:

The Chew Ranch Complex is bounded on the north by a line running east to west from the northwest point of a rock ridge above the garage(Point A) approximately 1,000 yards west to a point north of the "trout farm,"(Point B) on the west by a line approximately 425 yards long running north and south along a ridge that forms the western edge of the "trout farm," on the south by a line that runs southwest to northeast for approximately 1,000 yards from a point at the southwesterly corner of the Chew's hay meadow(Point C) to just east of the line's intersection with the Echo Park Road south of the loafing shed,(Point D) and on the east by a rock ridge that runs approximately southeast to northwest for 225 yards east of the corrals and loafing shed back to the point of the rock ridge north of the garage (Point A). These boundaries encompass all the pertinent structures and the cultural landscape that surrounds them.

State and County Location:

State(code)	County(code)
Colorado (08)	Moffat (081)